


## MEASURING BOLT CIRCLES



The easiest way to estimate the 5-lug bolt circle, is to measure from the back of a hole to the center of the second hole.

## MEASURING BACKSPACE

